

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

_		
Representativ	es Present During the Inspection:	
Company	Guy Davis Environmental Scientist	
OGM	Pete Hess Environmental Scientist III	

Inspection Report

Permit Number:	C0150009		
Inspection Type:	COMPLETE		
Inspection Date:	Friday, February 09, 2007		
Start Date/Time:	2/9/2007 8:25:00 AM		
End Date/Time:	2/9/2007 10:00:00 AM		
Last Inspection:	Monday, November 13, 2006		

Inspector: Pete Hess, Environmental Scientist III

Weather: <u>Cloudy, warm; 30's F.</u> InspectionID Report Number: <u>1210</u>

Types of Operations

Reprocessing

Accepted by: whedberg

3/7/2007

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO
Site: TRAIL MOUNTAIN MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

^		-4 4	A		
Сu	rrer	1T /	\cr e	ead	es

3,539.00	Total Permitted
10.69	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

Other

✓ Federal
✓ Underground

✓ State
□ Surface

□ County
□ Loadout

✓ Fee
□ Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the timely submittal of water monitoring data to the Division database, and thus, continues to meet the Special Permit condition included as Attachment "A" of the current State permit.

The site remains in temporary cessation status.

There are no compliance actions pending.

Most of the snow at this site has melted off.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Date

Monday, February 12, 2007

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150009 Inspection Type: COMPLETE

Inspection Date: Friday, February 09, 2007

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓			
2.	Signs and Markers	V			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	V			
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	V			
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	V			
14.	Subsidence Control	V		✓	
15.	Cessation of Operations	V			
16.2	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓		V	
20.	Air Quality Permit	V			
21.	Bonding and Insurance	V			
22.	Other	✓		V	

Inspection Continuation Sheet

Permit Number: C0150009 Inspection Type: COMPLETE

Inspection Date: Friday, February 09, 2007

Page 3 of 3

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Messrs. John Christensen, P.E., and Rick Cullum, R.L.S., performed the fourth quarter of 2006 impoundment inspection for the Trail Mountain Mine sediment pond on December 18, 2006. There were no unstable conditions or structural weaknesses noted by the Permittee's qualified individuals. The inspection report, which was completed on December 28, 2006 made note that the pond had 0.31 acre feet of sediment storage capacity remaining prior to reaching the 60% clean out elevation. The report was certified by Mr. Christensen and Mr. Cullum on January 23, 2007.

14. Subsidence Control

No mining has occurred at this site since 2001; all subsidence over the secondary extraction areas has stabilized. No further deformation is anticipated.

19. AVS Check

A change of ownership took place in March 2006. The new owners have since submitted and received Division approval of the Chapter One ownership and control information. Mid-American Energy Holdings Company is the new owner.

22. Other

All portal barricades remain effective; no tampering has been noted.